

THE PORT AUTHORITY OF NY & NJ

July 26, 2016

United States Environmental Protection Agency
Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866

Attn: NESHAP COORDINATOR


Re: NEWARK LIBERTY INTERNATIONAL AIRPORT
AVIATION FUEL SYSTEM MODIFICATIONS AF PIPE
ASBESTOS COATING REMOVAL
OPERATOR PROJECT #: 154.183

Dear Madam/Sir:

Our courtesy for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,



Uday Mehta, Manager
Environmental field Operations
Construction Management Division

Cc: Project File (EPA-2471)
Non-RACM Notification File

UM/fl

241 Erie Street
Room 238
Jersey City, NJ 07310
T: 201 595 4892

U.S. Environmental Protection Agency

Notification of Demolition and Renovation

Operator Project #: 154.183		Postmark:		Date Received: 07/26/2016		Notification #: EPA-2471	
I. Type of Notification (O=Original R=Revised C=Canceled) O							
II. Facility Information (Identify owner, removal contractor, and other operator)							
Owner Name: THE PORT AUTHORITY OF NY & NJ							
Address: 241 ERIE ST. ROOM 236							
City: JERSEY CITY		State: NJ		Zip: 07310			
Contact: R. CAMPIONE, FACILITY SUPERVISOR, ASBESTOS OPS						Telephone: 973-622-0800	
Removal Contractor: PINNACLE ENVIRONMENTAL CORP							
Address: 200 BROAD STREET							
City: CARLSTADT		State: NJ		Zip: 07072			
Contact: RAY KINSELLA						Telephone: 917-887-3604	
Other operator: N/A							
Address:							
City:		State:		Zip:			
Contact:						Telephone:	
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) R							
IV. Is Asbestos Present? (Yes/No) YES							
V. Facility Description (include building name, number, floor, and /or room number):							
Building Name: NEWARK LIBERTY INTERNATIONAL AIRPORT							
Address: NEWARK LIBERTY INTERNATIONAL AIRPORT							
City: NEWARK		State: NJ		County: ESSEX			
Site Location: AVIATION FUEL SYSTEM MODIFICATIONS - EXTERIOR AF PIPE REMOVAL							
Building Size: EXTERIOR FUEL FARM		# of Floors:		Age in Years: +50			
Present Use: FUEL TRANSFER				Prior Use: FUEL TRANSFER			
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: BULK SAMPLING UTILIZING PLM METHODS							
VII. Approximate Amount of Asbestos, Including:					Nonfriable Asbestos Materials Not To Be Removed		Indicate Measurement
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed			Non-RACM To Be Removed	RACM to Be Removed	Cat I	Cat II	
Pipes 24" FUEL LINE 8" TO 18" OD			495 LN. FT.				Lnft: 495
Surface Area							Sqft: 0
Vol RACM Off Facility Component							Cuft: 0
VIII. Scheduled Dates Asbestos Removal				Start: 08/08/2016		Complete: 10/28/2016	
IX. Scheduled Dates DemolRenovation				Start:		Complete:	

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used:

**XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos
At the Demolition And Renovation Site:**

EXTERIOR NON-FRIABLE MINI ENCLOSURES

XII. Waste Transporter #1

Name: ATC INC.

Address: 2 MORICHES MIDDLE ISLAND ROAD

City: SHIRLEY

State: NY

Zip: 11967

Contact: KENNY SMITH

Telephone: 631-924-5050

Waste Transporter #2

Name: N/A

Address:

City:

State:

Zip:

Contact:

Telephone:

XIII. Waste Disposal Site

Name: MINERVA ENTERPRISES

Location: 9000 MINERVA ROAD

City: WAYNESBURG

State: OH

Zip: 44866

Telephone: 330-866-3435

XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below

Name:

Title:

Authority:

Date of Order:

Date Ordered To Begin:

XV. For Emergency Renovations

Date and Hour of Emergency:

Description of Sudden or Unexpected Event:

Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:

**XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable
Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:**


IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET
WIPING ALL AFFECTED AREAS

**XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the
Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available
for inspection**


(Signature of Owner/Operator)

07-28-16
(Date)

XVIII. I Certify That the Above Information Is Correct.


(Signature of Owner/Operator)

07-26-16
(Date)